


● Inflation, Overload, High Speed, Braking

● The diagram below shows the effect of each part caused in a condition of under-inflation, overload, excessive high speed, braking



● Below indicates the phenomenon caused by the certain factor

